

HOW TO MONITOR AND RESPOND TO SIS MACHINE DISPLAYED ALERTS

| | |
|-------------|---|
| STDBY CALI | STANDBY CALIBRATING to skin or wound. |
| CONTACT OK | Electrode CONTACT OK . |
| CONTACT LOW | Electrode CONTACT LOW statistically. |
| CNTCT FLUC | Electrode CONTACT FLUCTUATING in short time-frame. |
| CIRC BREAK | Effective or physical CIRCUIT BREAK . |
| BATT LOW | BATTERY LOW charge. BATTERY CHARGE LED <u>on constantly</u> , not flashing. |
| NO CALI | NO CALIBRATION possible. |
| VOLT ALERT | High Output VOLTAGE ALERT . |

